



CPC Report
Riverview - FL0204



11/21/2024 - 12/17/2024

Must	More	Mod	Mod Max	Total Cars
3945	2090	694	546	
54.23%	28.73%	9.54%	7.51%	7275

Atlas Rep:Mike Garcia

Manager: Kevin Schildbach

Product	Application	Unit Price	On Hand	Delivered	Gallons Used	Cost	Must	More	Mod	Mod Max	Cost/App	mL/App
UHP	Presoak	\$99.13	31.25	20	18.75	\$371.74	\$201.58	\$106.79	\$35.46	\$27.90	\$0.0511	9.8
Scentsations	Scent	\$177.00	7.25	5	5.75	\$203.55	\$110.38	\$58.48	\$19.42	\$15.28	\$0.0280	3.0
Amplify	CTA	\$138.96	15	25	15	\$416.88	\$226.06	\$119.76	\$39.77	\$31.29	\$0.0573	7.8
Atomic Cond.	Lava	\$131.87	8.5	5	1.5	\$39.56	X	X	\$22.14	\$17.42	\$0.0319	4.6
Ultra Glide	Wrap Foam	\$144.50	12	0	2	\$57.80	\$31.34	\$16.61	\$5.51	\$4.34	\$0.0079	1.0
Atomic Polish (B)	Tri Foam	\$163.00	7.75	10	9.25	\$301.55	\$163.52	\$86.63	\$28.77	\$22.63	\$0.0415	4.8
Atomic Polish (R)	Tri Foam	\$163.00	7.5	5	7.5	\$244.50	\$132.58	\$70.24	\$23.32	\$18.35	\$0.0336	3.9
Atomic Polish (Y)	Tri Foam	\$163.00	8	5	9	\$293.40	\$159.10	\$84.29	\$27.99	\$22.02	\$0.0403	4.7
Turbo Low	Low pH	\$94.13	10	0	2.5	\$47.07	\$25.52	\$13.52	\$4.49	\$3.53	\$0.0065	1.3
Carnauba Maxx	Hot Wax	\$178.63	11	10	3.5	\$125.04	X	\$125.04	X	X	\$0.0598	6.3
C2	Ceramic	\$209.63	8	5	2	\$83.85	X	X	\$46.93	\$36.92	\$0.0671	6.1
Bahama Breeze	Rain Repel	\$212.50	7	0	3	\$127.50	X	\$80.02	\$26.57	\$20.91	\$0.0383	3.4
DX90	Drying Agent	\$184.00	11.5	20	12	\$441.60	\$239.47	\$126.87	\$42.13	\$33.14	\$0.0607	6.2
Graphene	Graphene	\$238.00	8.25	5	0.75	\$35.70	X	X	X	\$35.70	\$0.0079	5.1
Mod Shine	Tire Shine	\$725.00	23	0	9	\$217.50	X	\$136.51	\$45.33	\$35.66	\$0.0641	10.0
A la cart						Cost/Car	\$0.33	\$0.43	\$0.53	\$0.60		
Tire Shine	61					Blended CPC			\$0.40			
Ceramic	9											
Graphene	16	Site Notes:		Riverview CPC Site Visit Review: Good visit today. Dropped off chemical, conducted								

Site Notes:

Riverview CPC Site Visit Review: Good visit today. Dropped off chemical, conducted inventory count for CPC reporting, organized/consolidated containers, and performed tunnel audit. Identify salt leak from brine tank at softener. Tire brush/rocker hydraulic power pack leaking fluid near filter. Adjusted graphene applicators for even application. Lava was not foaming, checked inserts and looks to have been cross contaminated with red polish, swapped all 3 inserts for lava and good to go. Overall site is clean and orderly. Cars are coming out clean, dry, and shiny.