



CPC Report
Riverview - FL0204



12/17/2024 - 1/27/2024

Must	More	Mod	Mod Max	Total Cars
5995	3128	938	798	
55.21%	28.81%	8.64%	7.35%	10859

Atlas Rep: Tito

Manager: Kevin Schildbach

Product	Application	Unit Price	On Hand	Delivered	Gallons Used	Cost	Must	More	Mod	Mod Max	Cost/App	mL/App
UHP	Presoak	\$99.13	27.25	20	24	\$475.82	\$262.69	\$137.06	\$41.10	\$34.97	\$0.0438	8.4
Scentsations	Scent	\$177.00	8.75	5	3.5	\$123.90	\$68.40	\$35.69	\$10.70	\$9.11	\$0.0114	1.2
Amplify	CTA	\$138.96	10.25	10	14.75	\$409.93	\$226.31	\$118.08	\$35.41	\$30.12	\$0.0378	5.1
Atomic Cond.	Lava	\$131.87	11	5	2.5	\$65.94	X	X	\$35.63	\$30.31	\$0.0380	5.5
Ultra Glide	Wrap Foam	\$144.50	9.25	0	2.75	\$79.48	\$43.88	\$22.89	\$6.87	\$5.84	\$0.0073	1.0
Atomic Polish (B)	Tri Foam	\$163.00	10.75	10	7	\$228.20	\$125.98	\$65.73	\$19.71	\$16.77	\$0.0210	2.4
Atomic Polish (R)	Tri Foam	\$163.00	9.5	10	8	\$260.80	\$143.98	\$75.13	\$22.53	\$19.17	\$0.0240	2.8
Atomic Polish (Y)	Tri Foam	\$163.00	7.75	5	5.25	\$171.15	\$94.49	\$49.30	\$14.78	\$12.58	\$0.0158	1.8
Turbo Low	Low pH	\$94.13	10.75	5	4.25	\$80.01	\$44.17	\$23.05	\$6.91	\$5.88	\$0.0074	1.5
Carnauba Maxx	Hot Wax	\$178.63	8	5	8	\$285.81	X	\$285.81	X	X	\$0.0914	9.7
C2	Ceramic	\$209.63	10.5	5	2.5	\$104.82	X	X	\$56.63	\$48.18	\$0.0590	5.3
Bahama Breeze	Rain Repel	\$212.50	7.25	5	4.75	\$201.88	X	\$129.82	\$38.93	\$33.12	\$0.0415	3.7
DX90	Drying Agent	\$184.00	10	20	21.5	\$791.20	\$436.80	\$227.91	\$68.34	\$58.14	\$0.0729	7.5
Graphene	Graphene	\$238.00	8	0	0.25	\$11.90	X	X	X	\$11.90	\$0.0017	1.1
Mod Shine	Tire Shine	\$725.00	38	30	15	\$362.50	X	\$233.12	\$69.91	\$59.47	\$0.0725	11.4
A la cart						Cost/Car	\$0.24	\$0.36	\$0.46	\$0.47		
Tire Shine	136					Blended CPC			\$0.31			
Ceramic	42											
Graphene	44											
				Site Notes:	Riverview CPC Site Visit Review: Good visit today. Dropped off chemical, conducted							

Site Notes:

Riverview CPC Site Visit Review: Good visit today. Dropped off chemical, conducted inventory count for CPC reporting, organized/consolidated containers, and performed tunnel audit. Identify salt leak from brine tank at softener. Tire brush/rocker hydraulic power pack leaking fluid near filter. Adjusted graphene applicators for even application. Lava was not foaming, checked inserts and looks to have been cross contaminated with red polish, swapped all 3 inserts for lava and good to go. Overall site is clean and orderly. Cars are coming out clean, dry, and shiny.